

Imperfections – deformation and microstructures in polycrystals

Sébastien Merkel
Professor, Physics Department
UMET Laboratory (Unité Matériaux et Transformations)
sebastien.merkel@univ-lille.fr

Imperfections - deformation and microstructures in polycrystals


7- On the hexagonal-close-packed crystal structure

Metals with an hcp structure:

- Zirconium, titanium, magnesium, zinc, ϵ -iron ($P > 15$ GPa)

Interest :

- Zirconium alloys(zircalloy) in nuclear industry (fuel rods in nuclear reactors)
- Titanium alloys: airplane engines
- Magnesium: car industry (lighter than steel)
- ϵ -iron: geophysics, Earth's inner core




4 indices notation

Vectors a_1 , a_2 and a_3 are equivalent and non-orthogonal to each other


- Definition of Miller indices on 3 non-orthogonal axes (a_1 , a_2 et c): can be used but will hide symmetry operations
- Definition of Miller indices on 3 orthogonal axes (a_1 , a_2 et c) can be used but it is easy to use (loss or symmetry elements, difficult to correlate to the crystal structure).

Hence: 4 indices notation:

- For planes: $(hkil)$ avec $h+k+l=0$;
- h , k , and l are identical to those of the 3 indices notation
- For direction: conversion between 3 and 4 indices is more complex
 - $u = (2u'-v')/3$; $v = (2v'-u')/3$; $t = -(u+v')$
 - $w = w'$
 - $[uvwt]$ with $u+v+t=0$



Direction examples (1)




Practice:

Pot the $[2\bar{1}\bar{1}0]$ and $[1\bar{1}\bar{2}0]$ directions

Al all other equivalents


Direction examples (2)




Practice:
Plot the $[10\bar{1}0]$ and $[01\bar{1}0]$ directions and all other equivalent directions.

- Also note
- For directions in the basal plane: $[hki0]$ is orthogonal to the $(hki0)$ plane.
 - It is not true for $(hkil)$ planes if $l \neq 0$.


Basal and prismatic planes



Pyramidal planes



Stereographic projection



Barret & Massalski, Structure of Metals,
Pergamon (1980)

c/a parameter

The c/a parameter is related to the compact nature of the structure

- True compact structure: $c/a = 1.633$
- The c/a parameter has a large influence on plastic deformation in hcp metals

Métal		c/a
Cadmium	Cd	1,886
Zinc	Zn	1,856
Magnésium	Mg	1,623
Cobalt	Co	1,623
Rhéinium	Re	1,615
Zirconium	Zr	1,592
Osmium	Os	1,589
Titane	Ti	1,587
Béryllium	Be	1,568